

























检查夹具用插入销

一概要一

■检查夹具用插入销选择表

类型 形状	形状		页码	
	小头型	大头型		
直柱型	圆形			P.1521
				P.1523
	多棱形			P.1523
				P.1525
	缺圆型		—	P.1527
	圆形(加长)		—	P.1529
	粗径	—		P.1529
	外螺旋型			P.1530
				P.1530
	划线型	直柱型		
				
中空型			—	
锥型	圆形			P.1533
	外螺旋形			P.1537